Office of the Director General of Police and Director General

Karnataka State Fire and Emergency Services and State Disaster Response Force No. 1, Annaswamy Mudaliar Road Bengaluru - 560 042



Phone No: 080 25570733

22971501 22971507

Fax: 22942108

Date: 5 -04-2025

No.GBC(2)2915/2024 E-Office Com No.42475.

*J*6,

The Secretary,
Akshara International Public School,
Akshara Educational and Development Trust ®,
Kowdle,
Maddur taluq,
Mandya District 571425.

Sir,

Sub: Issue of 'Fire Advisory Certificate' to the Educational Building 'Akshara International Public School' situated at Kowdle, Maddur taluq, Mandya District.

Ref: Your Request Letter dated:19-09-2024.

<<<<>>>>>

With reference to the subject cited above, the District Fire Officer, Mandya Fire Station, Mandya District inspected the Educational Building 'Akshara International Public School, situated at Kowdle, Maddur taluq, Mandya District on 30-10-2024 with respect to fire prevention, firefighting and evacuation measures to be complied in the above premises and submitted the details as follows: -

A. Details of the building / premises: -

5/4/25

Managa and Addison - City	T	
Name and Address of the Applicant.	·	The Secretary, Akshara International Public School, Akshara Educatioonal & Development Trust (R), Kowdle, Maddur Taluk, Mandya District-571425.
Name and Address of the premises.		Akshara International Public School, Akshara Educatioonal & Development Trust (R), Kowdle, Maddur Taluk, Mandya District-571425.
Name and address of the Building owner		The Secretary, Akshara International Public School, Akshara Educatioonal & Development Trust (R), Kowdle, Maddur Taluk, Mandya District-571425.
	Name and Address of the premises. Name and address of the Building owner	Name and Address of the premises: Name and address of the Building owner

Page 1 of 7

04	Number of buildings	:	01 No School Building only.		
05	Number of floors	1	Ground floor and 04 upper floors.		
06	Floor-wise details of occupancy: -				
			Ground Floor: - 13-Class room, Admin Office, Principal Room, Staff room and 02 Wash rooms. First Floor: - 16 Class room, And 02 Wash rooms. Second Floor: - 16 Class room, And 02 Wash rooms. Third Floor: - 16 Class room, And 02 Wash rooms. Third Floor: - 16 Class room, And 02 Wash rooms. Fourth Floor: - 05 Class room.		
07	Height of the building	:	16.10 mtrs		
80	Site area	:	8064.81. Sq Mtrs		
09.	Built-up area of each floor: -		Ground Floor: - 1196.00 Sq Mtrs. First Floor: - 1196.00 Sq Mtrs Second Floor: - 1196.00 Mtrs Third Floor: - 1196.00 Sq Mtrs Fourth Floor: - 414.40 Sq Mtrs Total 5195.40 Sq.mtrs		
10.	Total built-up area		5195.40 Sq.mtrs.		
11.	Surrounding properties: -				
	West (Front)	:	18.00 Mtr Mandya to Yadiyur main Road		
	East (Rear)	•	Agriculture Land		
	North (Side)	8.1	Agriculture Land		
	South (Side)	1.18	Agriculture Land		
12.	Set-back area available around the building: -				
	West (Front)	:	03.00 Mtrs		
	East (Rear)		05.00 Mtrs		
	North (Side)		10.00 Mtrs		
	South (Side)		05.00 Mtrs		



<u>B.</u> On inspection of this educational premises, the following fire prevention, firefighting and evacuation measures recommended are considered absolutely essential from fire safety point of view: -

SI. (1)	LAISTING				Recominendations
1.					(04)
	Accessibility to the premises	The premise from 18.00 Yadiyur main the Western hardened to 0 45,000 kgs.	Mt ro Side	The Requirement is complied with.	
2.	No. of entrances	01 Entry cum	Exit	The Requirement is complied with	
3.	Width of entry / exit	06.00 Mtrs		The Requirement is complied with.	
4.	Diesel generators.	Provided 0 Generator of to supply alte the emergence building.	30 rnat	The Requirement is complied with.	
5.	No. of staircases	Nos. of	1	02 nos.	The Requirement is
	available	staircases			complied with.
	e eller	Width of staircases		01.50 mtrs.	
	o ream pr	Width of treads		30 cms	
		Height of risers	i	15 cms	
		No. of riser / flight		12 nos.	
		Height of handrails	÷	1.00 mtr.	
		Head room clearance	i	3.10 Mtrs.	
6.	Fire extinguisher	02 water mis	t ex	The Requirement is	
		9 Itrs capaci	ty i	complied with.	
	eral of Police	staircase landi A.One medextinguisher & one extinguisher capacity progenerator.	ng. cha of s		
Gent Sol Ke	mataka State	B.One CO extinguisher	, (type fire of 4.5 kgs	to the second
Fire	Services &	capacity	pro	vided near	(2) magazina 4 2 m

514125

Page **3** of **7**

		electrical panel board.	
	the strain to Info	C. 15 Nos ABC type fire extinguisher of 6 kgs capacity installed in School Building. The Systems was tested during inspection and found working satisfactorily.	La
7.	Public address system	Provided with one way communication facility at each floor near each Staircase landing with its console at the control room located on the ground floor.	The Requirement is complied with.
Sol I	First aid Hose reel hose with Down Comer system amataka State 2 Emergency Services	Provided with 02 No Down comer System with Single Headed Internal Hydrant line shall be 100 mm internal dia. and will be of "G.I. C" class pipe. From each hydrant single headed hydrant outlet has been provided with 2 No's delivery hose pipes, each of 15 mtrs. Length with gunmetal branch pipe have been provided inside each hose cabinet near each outlet and 02 numbers. Hose Reel Hose system provided in each floor provided with 07 Nos hose real hose drums near the staircase. The hose reel hose of min 19 mm size and of 30 Mtrs length have been provided to reach the farthest point of each floor and shut off branch having a nozzle of 5mm size. The hose reel hose should be connected at each landing of building. This system was connected to a terrace tank of 40,000 ltrs. Capacity with a Booster pump capable of delivering 900 liters of water per minute. The Systems was tested during inspection and found working satisfactorily.	The Requirement is complied with.

9.	Terrace tank over respective tower terrace/Undergroun d Tanks	Provided with 40000 Litre Capacity of Terrace tank.	The Requirement is complied with. (In this 25,000 Water tank should be kept exclusively fire fight purpose).
10.	At the terrace tank level with minimum pressure of 3.5 kg/cm ² .	Provided with one booster pump near overhead tank of capable of delivering 900 liters per minutes. The System Connected to Alternative Source of Power Supply. The Systems was tested during inspection and found working satisfactorily.	The Requirement is complied with.
11.	Manually operated electronic Fire alarm system.	Provided with 07 no Manually operated electrical fire alarm system with Manual call points (Break Glass type) Near each staircase landings at each floor with its console at control panel room at ground floor area & system haven been connected to the alternate power supply.	The Requirement is complied with.
12.	Provided provide Fire control room at ground floor	Provided Fire control room at ground floor.	The Requirement is complied with.
13.	Escape routes	Provided with Marking Directions in which the Students & Staff have to move in the event of any emergency shall be indicated in the corridor during evacuation. It is written in luminous paint in every floor of building.	The Requirement is complied with.
the Diffe	Fire order Kernataka State Fire & Emergency Services	A notice board written in bold letters indicating the action to be taken by the Students & Staff in case of any emergency is displayed near staircase and the notice board is contain telephone number of Maddur Fire Station 08232-200098 & 101 and ambulance service & Police station at near staircases of building as displayed.	The Requirement is complied with.
8	Sengaluu \ S	14/25 20/4/2	Page 5 of 7

15.		COPTA S	ec-4 direction No	The Requirement is
	boards.	Smoking ar	ea Smoking here is board written in	complied with.
175	enould be see	languages.	Kannada both This is displayed at entry / exit of each	
10		floor.	The of Cacif	T 100 100 100 100 100 100 100 100 100 10
16.	Firefighting training	Not Imparted	naviab la alos gazo ce territaria algunia ce betaggazo de este betaggazo de este este este est norregan unnub norregan un	40% Occupants should get trained in fire prevention & firefighting system at R.A. Mundkur Academy Bannerghatta Road Bangalore – 560029 OR Regional Training Center, Hebbala, Mysuru at an early date.
	Fire precautionary measures.		A. Explosive and should not be s	
			UPS room, Elec	ctrical panel area class
			rooms, laborat	ory & electrical sum
			panel premises.	
	The Requirement		and around the avoided.	f combustible waste in e premises should be
	THE RESIDENCE OF THE PARTY OF T		C. The exit ways	shall be always kept
	tine literature and the difference of the differ		D. Liquefied petrol	obstruction. eum gas should not be
			stored in the buil	dina.
			latched during w	not be kept locked / /orking hours and shall
			F. During the class	hours the class room e locked from inside to
	one supeR and		outside.	e locked from inside to
			G. As per Hon'ble S	upreme Court order all
			handle safety	affs shall be trained to equipment: initiate
	-9	enillimene de	students in the e	uation and protect their event of fire and other
	peral of A		observe the Fire	the school shall Safety Day on April ar by conducting Fire
30	Karnataka State		Safety drills with service department	co-ordinate with fire

514/25

As such the Karnataka State Fire and Emergency Services department is issuing 'Fire Advisory Certificate' to the Educational Building 'Akshara International Public School, situated at Kowdle, Maddur taluq, Mandya District from Fire prevention, Firefighting and Evacuation point of view subject to the compliance of below mentioned conditions within 03 months from the date of issue of Fire Advisory Certificate.

 COTPA Sec-4 direction No smoking area smoking here is an offence board should be writer in English & Kannada both languages shall be prominently displayed at inside the entry /exit of each floor.

2. A Fire Nodal Officer shall be nominated either from teaching or non-teaching staff.

- 3. A Fire siren shall be installed in the premises to inform the students in case of a fire emergency and evacuate the area.
- 4. At least 40% of teaching & non-teaching staff should be got trained in fire prevention and firefighting evacuation measures at R.A.Mundkur Fire &Emergency Services Academy, Bannerughatta Road, Bangalore-560 029 or Regional Training centre.

Note: -

- 1. This is only the "Fire Advisory certificate" issued by the Fire Department from fire safety view of the low-rise already constructed Building. This shall not be considered as No Objection Certificate for the Building.
- 2. After completion of all the firefighting installations as advised in Fire Advisory Certificate, 'Fire Advisory Compliance Certificate' shall be obtained from the Fire and Emergency department.

Draft approved by the D.G.P. & D.G.

Karnstake State
Fire & Emergency
Services
Bengaluru
550 042

Yours faithfully,

(T.N.Shivashankara)

Director,
For Director General of Police and
Director General,
Karnataka Fire & Emergency Services.

Copy to District Fire Officer, Mandya Fire Station, Mandya District.